



timeware®

HR, Time and Attendance Software

timeware® Bell Driver

Datasheet for the X-401 bell driver

Overview

With our introduction of Suprema hardware as the primary source of our 'clocking machines', we have had to change our method of triggering a bell or claxon. We are fully moving away from timeware® providing this solution and are instead utilizing an external relay with a separate web interface that a customer can control themselves.

Point to note


This is to be self-installed by the customer. timeware® only recommends the devices to the customer and they purchase/fit themselves.

Recommended 'Bell Driver'

We currently recommend the X-401 Dual Relay and Input Module which can be purchased from www.controlbyweb.com

Full specification can be found here

<https://www.controlbyweb.com/x401/>



Specifications

Compatible with any bell that ranges between 4v – 26v DC

Network connection required

Web interface used over your network to configure bell times

Self-Installed



Company Name: timeware (UK) Ltd.

Registered Office: 3 Fieldhouse Road, Rochdale,
Greater Manchester, OL12 0AD.

Company Reg. No: 05886806.

Registered in: England.

t2-0477: Copyright NMD³ Ltd

www.timeware.co.uk
support@timeware.co.uk
+44 (0) 1706 658222